



>>>

CODE	DIM dx <sub>d</sub> ,xd [mm]	D [mm]	D1 [mm]	L [mm]	I [mm]	L1 [mm]	I1 [mm]	PN [bar]
1013051025001	50x25x50	96	55	265	104	98	63	16
1013051032001	50x32x50	96	63	265	104	107	68	16
1013051040001	50x40x50	96	80	265	104	124	94	16
1013064025001	63x25x63	115	55	336	133	116	62	16
1013064032001	63x32x63	115	63	336	133	113	67	16
1013064040001	63x40x63	115	80	336	133	136	94	16
1013064051001	63x50x63	115	96	336	133	143	111	16
1013076051001	75x50x75	125	96	365	136	166	120	16
1013076064001	75x63x75	129	115	365	136	170	123	16
1013091064001	90x63x90	155	115	415	154	192	133	16
1013091076001	90x75x90	155	129	407	154	195	136	16
1013111076001	110x75x110	183	129	535	203	220	149	16
1013111091001	110x90x110	183	155	535	203	231	156	16